



Glass and Polymer  
Technologies

# Surfaces

Surface treatment	Remarks
Deburring	Most effective but also most expensive method to get rid of burrs and sharp edges. Manual process.
Blasting	Well suited for amorphous and hard materials. Caution: cloud formation.
Vibratory finishing	The amount of removed material strongly depend on the geometry of the part.
Polishing	Good results are possible on hard materials (PMMA, POM, PEEK, etc.).
Diamond polishing	Especially suited for PMMA.
Rubbing	Possible only in bores.